

Kelley Aviation

Additional Annual Inspection Charges



Additional Charges & Fees

All Aircraft

Single & Twin Engine Aircraft

- A one-time \$500 AD compliance research fee will be added to the annual inspection flat rate for first-time customers.
- Any maintenance or repairs identified during the annual inspection that fall outside the scope of the flat-rate inspection will be billed separately for labor and parts.
- A \$200 fee will be added to the flat-rate annual inspection for aircraft equipped with onboard oxygen systems.
- A \$200 fee will be added to the flat-rate annual inspection for aircraft equipped with pressurization systems.
- Engine oil, oil filters, intake filters, vacuum filters and avionics filters are not included in the flat-rate annual inspection and will be billed separately.

NOTE:

For owner-assisted annual inspections, labor performed by the aircraft owner will be credited at a rate of \$20.00 per hour.